



AMERICAN MGB ASSOCIATION

TECHNICAL SECTIONS

on CD-ROM
VOLUME III
(OCTAGON YEARS 1997 THRU 2007)

Volume I and II, covering earlier publications also available from the AMGBA

PUBLISHED BY THE AMGBA
5433 N. ASHALND AVE., CHICAGO, IL 60640 U.S.A.
Phone: (773) 769-7084
FAX: (773) 769-3240
email: info@mgclub.org
www.mgclub.org or www.amgba.com

AMGBA TECHNICAL SECTIONS

<u>PUBLICATION</u>	<u>PAGE</u>
1997 December	11
1998 February	16
1998 April	20
1998 June	23
1998 October	30
1999 February	36
1999 April	41
1999 August	50
1999 October	57
1999 December	64
2000 February	70
2000 April	76
2000 June	82
2000 August	86
2000 October	92
2000 December	98
2001 February	105
2001 April	113
2001 June	119
2001 August	126
2001 October	134
2001 December	141
2002 February	148
2002 April	154
2002 June	161
2002 August	169
2002 October	176
2002 December	183
2003 February	190
2003 May	198
2003 August	206
2003 October	213
2003 December	220
2004 March	227
2004 June	233
2004 August	239
2004 October	249
2004 December	257
2005 February	261
2005 May	265
2005 August	273
2005 October	276
2005 December	278
2006 March	281
2006 June	285
2006 August	288
2006 October	291
2006 December	294
2007 March	297
2007 June	300
2007 August	302
2007 October	305
2007 December	307

NOTE: Please note the ads that may appear here are reproduced as they originally appeared in that issue and therefore may be several years old and are not to be relied on for prices or information.

Nothing may be reproduced in whole or in part without the written permission of the publisher. The views of contributing writers are their own and not necessarily the views of the AMGBA. Readers are warned in following any advice given and no liability either express or implied is assumed by the advice or opinions given by individual contributors or the AMGBA. Copyright © 2016, AMGBA

ARTICLE INDEX

Publication references in which AMGBA publication the article originally appeared and the year; the page number it was on and if a Question and Answer (Q & A), its position on the page and page number in this issue.

SUBJECT/ <u>ARTICLE</u>	ORIGINAL PUBLICATION		PAGE NUMBER	
	<u>ISSUE</u>	<u>PAGE</u>	<u>Q & A</u>	<u>THIS ISSUE</u>
Body/Exterior				
Bonnet insulation	2000 December	23	1	98
Bumper beautification	2000 June	28		83
Bumper preservation	2002 August	26	1	170
Changing color and car value	2004 March	33		232
Chrome bumper conversion	2003 February	32		195
Colors	2000 October	25	1	92
Door hinges	1999 December	33		69
Door removal	2001 April	24	4	113
Dull rubber bumpers	2005 August	20	1	273
Fasteners	2002 October	32		181
Fender substitution	1999 April	25	4	44
Fender & Windshield installation	2002 April	28		157
Front end replacement	2004 August	28	1	243
Gearshift boot bolts	2000 December	24	4	99
Grille replacement	2006 December	21	2	295
Headlight rim removal	2000 October	26	2	93
Hood latch	2001 June	26	4	121
Mirror replacement	2000 February	29	1	72
New paint job problems	2006 June	20	1	285
Painting dos and don'ts	2001 August	27		130
Painting your MGB	2000 April	28		78
Rocker panel replacement	2001 August	23	3	126
Rust and corrosion	1999 August	29		53
Serial number for color	1998 February	27	1	17
Soft top installation	2004 August	27	1	242
Solid taillight lens	2003 December	28	1	223
Steering wheel removal	1999 October	25	1	57
Stamped VIN number	2001 April	24	1	113
Stow away top	2000 August	25	1	86
Top header rail	1999 December	25	3	64
Top replacement	2002 August	25	1	169
Top tips	2003 May	32		203
Trunk lid	2002 December	29	1	187
Windshield crack	2007 August	20	1	302

SUBJECT/ ARTICLE	ORIGINAL PUBLICATION			PAGE NUMBER
	ISSUE	PAGE	Q & A	THIS ISSUE
Brakes				
Bleeding brakes	2000 August	26	2	87
Brake cylinder rebuilding	1998 October	26	1	31
Brake drums	2000 August	27		88
Brake cylinder	2001 October	24	1	135
Brake pads	2002 December	28	2	186
Braked locking	2002 August	32		173
Build your own EasyBleed	1999 February	28		38
Front brakes not releasing	2003 August	32		211
Squeaky brakes	1999 August	28		52
Carburetion/Fuel System				
Air filter dirt	2000 April	26	1	77
Air filter reduced	2000 April	25	4	76
Carb conversion	2001 December	28		144
Carb replacement kit	2000 February	28	2	71
Carb fluid	2004 December	19	2	257
Carburetor choices	2000 December	27		102
Carburetor modification	2000 June	32		84
Choke cable replacement	2006 December	21	1	295
Dual SU Conversion	2006 March	22		284
Float problems	2005 December	20	2	278
Flooded engine	2002 August	29	2	172
Fuel injection the MGB	1998 June	27		26
Fuel leaking	1998 October	25	3	30
Fuel pump	1999 August	26	1	51
Fuel pump noise	2006 August	20	2	288
Fuel pump ground	1999 February	25	1	36
Fuel pump running on	2003 August	33		212
Fuel starvation	2001 August	25	4	128
Fuel tank cleaning	1999 August	25	1	50
Fuel tank sending unit	1999 October	25	5	57
Fuel vapor lock	2005 May	23	2	265
Gas smell	2002 October	24	1	176
HS-4 jets	2005 February	19	1	261
HS-4 to HS-6 carbs	2001 December	28		144
K & N air filters	2004 December	20	2	258
Rebuild carburetor	2000 December	23	2	98
SU polarity	2002 June	29		167
Tuning your SU carbs	2001 April	27		115
Twin SU conversion	2000 February	28	1	71
Unleaded fuel	2002 August	32		173
Weber carb	1999 April	25	1	44
Weber replacement	2003 August	28	2	209
Weber vs SU	2003 October	32		218

SUBJECT/ ARTICLE	ORIGINAL PUBLICATION			PAGE NUMBER
	ISSUE	PAGE	Q & A	THIS ISSUE
Cooling/Heating System				
Air conditioning system	2000 October	26	3	93
Cooling system emptying & refilling	1997 December	34		15
Coolant leakage	2005 October	20	2	276
Dual fans	2000 August	25	3	86
Hayden Rapid Cool	2006 August	20	1	288
Heat in the USA	1999 February	32		40
Keeping cool in summer	1998 October	27		32
More Heat	2002 June	28		166
Overheating	1999 December	25	1	64
Radiator bolts	2005 May	23	1	265
Radiator fans	2001 October	23	1	134
Running hot	2005 October	20	1	276
Stuck heater valve	2001 August	25	5	128
Thermostat blanking sleeve	2002 October	25	2	177
Water out of header tank	2000 October	36	1	97
Electrical				
12 volt battery	1999 December	26	1	65
12 volt battery conversion	2000 October	26	5	93
Aftermarket CD players	2004 October	32		254
Alternator regulator	2003 October	25	1	214
Antenna replacement	2005 February	22	2	263
Backup lights	2004 March	25	1	227
Battery cover fasteners	1999 October	33		62
Battery cut off switch	2005 December	26		280
Battery drain	1999 December	32		68
Battery drain part 2	2004 August	32		245
Battery drain revisited	2002 February	32		152
Battery drainage	2000 October	27		94
Battery dying	2000 February	26	1	76
Bosch alternator conversion	2000 December	25		100
Brake lights come on	1999 October	25	4	57
Changing points	2000 June	28		83
Dashboard rocker switch	2001 April	24	1	113
Directional lights	2004 August	23	4	239
Distributor conversion	2004 June	25	3	234
Distributor settings	2005 December	21	1	279
Electronic ignition conversion	1999 December	28		66
Flasher unit	2004 August	23	1	239
Front turn signal	2006 August	20	3	288
Fuel pump not connected	2007 Deember	20	1	307
Fuse box location	2004 August	28	2	243
Generator	2001 February	28		110
Headlights	2003 December	25	2	221
Horn problems	1999 August	25	3	60

SUBJECT/ ARTICLE	ORIGINAL PUBLICATION			PAGE NUMBER
	ISSUE	PAGE	Q & A	THIS ISSUE
Electrical (continued)				
Ignition lock	2004 August	24	3	240
Ignition switch fix	1999 December	33		69
Ignition parts replacement	1999 October	26	2	58
Maximizing the electrical system	1998 February	33		19
Multiple failings	2005 August	20	2	273
Petronix electronic ignition	2003 February	24	1	190
Points voltage	1999 April	26	1	45
Points wear	1999 October	26	1	58
Positive or negative ground	2007 August	20	2	302
Rear taillight problems	2007 October	20	1	305
Spark plug gaps	2002 February	24	2	149
Spark plugs	2000 October	25	3	92
Spark plug wires	2000 October	26	1	93
Speaker installation	1999 February	25	2	36
Steering columns switches	1998 February	27	2	17
Taillight and side marker lights	1999 October	25	2	57
Turn signal problems	1999 August	25	4	50
Turn signals not working	2000 April	25	2	76
Turn signal switch	2004 August	27	3	243
Voltage regulator	2007 June	21	1	297
Voltage regulator replacement	2007 March	21	3	297
Weak spark	2001 June	29		124
Wiper motor wiring	1998 April	26	2	20
Wipers parking	1999 February	26	1	37
Wipers move slowly	2001 June	24	3	119
Emission Controls				
Charcoal cannister removal	2007 December	20	2	307
Emission controls and performance	2007 August	21	1	303
Emission test	2007 March	21	1	297
Emissions update	2000 August	32		90
Hot catalytic converter	2004 October	24	3	249
Partial removal of emission controls	2004 August	29		244
Removing smog system	2000 June	27	3	82
Vacuum line holes	2000 December	24	2	99
Engine/Mechanical				
3 to 5 main bearing engine	2004 October	26	1	250
327 cu in conversion	2007 June	20	1	300
Accelerator cable	2003 August	25	2	207
Backfire on deceleration	2003 October	29		217
Backfiring	2000 October	25	2	92
Breather tube oil	2004 June	23	1	233
Car not starting	2005 August	21	1	271
Compression ratio	2000 October	32		96
Cranks slow	2001 February	26		108

SUBJECT/ ARTICLE	ORIGINAL PUBLICATION			PAGE NUMBER
	ISSUE	PAGE	Q & A	THIS ISSUE
Engine/Mechanical (continued)				
Cylinder head compression	2005 May	24	1	266
Cylinder head crack	2006 August	21	1	289
Cylinder head problem	1997 December	25	2	11
Engine miss	1999 December	25	4	64
Engine not restarting when warm	1997 December	25	3	11
Engine parts identification	2004 August	33		246
Engine rattle	2001 April	25	1	114
Engine rebuilding	2004 August	33		246
Engine shuts down	1999 October	25	3	57
Engine swap	2001 June	24	1	119
Exhaust manifold	1998 February	26	4	16
Excessive smoking	2007 December	20	4	307
Gray smoke	2001 April	25	3	114
Head bolts	2001 December	24	3	142
Head gasket blown	1998 February	26	1	16
Head torque sequence	2001 December	28		13
Idling problems	2001 February	23	1	105
Ignition	1997 December	28		13
Ignition (continued)	1998 February	28		18
Larger engine in Midget	2001 October	23	2	134
Lifters	2002 December	25	1	184
Manual choke	1998 April	27	1	21
MGB engine conversion	1999 October	29		60
Motor mounts	2001 June	25	1	120
Motor rebuild	2004 June	25	2	234
Not starting	2000 February	28	3	71
Peco exhaust system	2003 February	25	2	191
Pistons and head replacement	2000 April	25	3	76
Piston bore	2005 May	25	2	267
Pistons	1998 June	24	1	23
Restarting after warm	1999 December	25	2	267
Ring gear removal	2006 March	20	1	282
Rotary engine	2000 August	25	2	86
Running hot	1997 December	26	1	12
Setting dwell	1998 October	25	1	30
Setting timing	2001 October	25	1	135
Supercharging	2001 August	28		131
Startup problems	2006 October	20	1	291
Starting problems part 2	2004 August	26	1	241
Timing chain noise	2004 December	19	1	257
V8 conversions	2003 October	32		218
V8 conversion tips	1999 February	32		40
Valve clearance adjustment	2004 June	32		235
Valve gaps	2000 August	26	2	87
Warm starting problems	2000 December	23	6	98

SUBJECT/ ARTICLE	ORIGINAL PUBLICATION			PAGE NUMBER	
	ISSUE	PAGE	Q & A	THIS	ISSUE
Gauges					
Gauge loss	1999 December	26	2		65
Oil pressure gauge	1999 December	33			69
Gauge and voltage stabilizer	2000 April	25	1		76
Gauges operating sporadically	2001 December	24	1		142
Speedometer bounces	2004 August	26	2		241
Speedometer indicating wrong speed	2001 October	26	1		137
Tach readings	2004 August	27	2		242
General					
'75 MGB price	2007 October	20	3		305
After Car Storage	2006 October	22			293
Car buying tips	2003 May	32			203
Dating the MGB by Chassis Number	2006 March	7			281
Handy yet inexpensive tools	1999 October	34			63
Insurance	2002 December	32			188
Key replacement	1998 February	26	3		16
Keys	1999 February	25	3		36
Left hand to right hand drive	2004 August	24	2		240
Mechanic needed in NH	2000 February	28	5		71
Mechanic needed in PA	2000 February	29	2		72
MG value	2004 August	23	3		239
Restoration manual	2001 December	24	2		142
Running after storage	2001 April	24	5		113
Speedometer problems	1999 August	25	2		50
Storage for 15 years	2000 August	25	4		86
Tao of MG maintenance	1998 October	33			34
Things to look for in an MGB	2002 June	32			168
Interior					
Carpet kit installation	2001 June	28			123
Carpeting installation	1998 April	26	3		20
Collapsible steering wheel bearings	2004 March	27	4		228
Dripping under dash	2000 October	25	4		92
Passenger seat sensor	2006 August	22	1		290
Seatbelt interlock	2006 October	20	2		291
Seat rail adjusting	2004 June	33			237
Steering wheel replacement	2002 October	33			182
Window vent parts	2007 March	26	1		299
Window regulator	2006 October	21	1		282

SUBJECT/ ARTICLE	ORIGINAL PUBLICATION			PAGE NUMBER
	ISSUE	PAGE	Q & A	THIS ISSUE
Oil/Lubrication				
Correct engine oil	2004 March	29		230
Dirt on Oil	1999 April	17		41
Low oil pressure	1999 October	28		59
Low oil pressure part 2	2005 August	23		275
Low oil pressure readings	2004 August	24	1	240
Motor oils are not what they used to be	2007 March	22		298
Mysteries of Motor Oils	2000 February	32		73
Oil consumption	2001 February	24	2	106
Oil filter update	1998 April	33		22
Oil leak	2000 April	25	5	76
Oil leak at o-ring	2000 December	23	4	98
Oil filers	2000 April	33		81
Oil pressure	2000 October	27		94
Oil pressure drop	2006 December	22		296
Oil type	1998 June	25		24
Suspension/Handling				
A-arm bushings	2000 December	23	3	98
Axle removal	2003 December	32		225
Bushings cracked	1998 April	26	1	20
Clunking noise	2000 October	25	4	92
Clutch friction point	2000 June	27	2	82
Coil spring replacement	2001 June	25	1	120
Front end scraping noise	2004 March	25	2	227
Front suspension bearings	2004 March	29		230
Improving handling	2000 December	24	1	99
MGB suspension rebuild	1999 April	27		46
MGB tube shock conversion	2000 June	28		83
Rear axle replacement	2000 October	25	5	92
Shock damper fluid	1999 April	25	2	44
Springs	2001 August	32		132
Steering rack boots	2003 August	24	3	206
Strange handling problem	2004 August	23	2	239
Suspension conversion	2000 February	26	3	70
Tube shock conversion	2000 June	27	1	82
Veering to left	2006 December	20	4	295

SUBJECT/ ARTICLE	ORIGINAL PUBLICATION			PAGE NUMBER
	ISSUE	PAGE	Q & A	THIS ISSUE
Transmission/Handling				
5-speed conversion	2002 June	25	1	163
Bleeding clutch	2000 August	28		89
Clutch freeze	2004 December	23		260
Clutch pedal engagement	1997 December	25	1	11
Clutch linkage lube	1999 April	25	5	44
Clutch not engaging	2005 February	22	1	263
Clutch slipping	2002 June	24	2	162
Datsun tranny fit	2002 December	26	1	185
Frozen clutch	2002 February	28		151
Gear popping	2004 August	26	3	241
Hard shifting	2003 August	33		212
Inoperable overdrive	2000 June	27	4	82
Overdrive equipped	2000 April	26	2	77
Overdrive fit	2000 December	24	3	99
Overdrive installation	2004 June	23	2	154
Overdrive removal	2002 April	23	1	154
Overdrive repair	2001 December	34		146
Rattling noise	1998 February	26	2	16
Reverse gear shifting difficulty	2005 February	23		264
Shift pattern	2003 October	24	2	213
Slave cylinder leak	2007 March	21	2	297
Synchro problems	2006 December	20	1	294
Transmission rebuild	2006 March	20	1	282
Transmission removal	2003 May	28	1	301
Transmission substitution	2007 October	20	2	305
Transmission oil	2006 December	20	3	294
Wheels/Tires				
Front tires wearing	2005 December	20	1	278
Pitted L.E. wheels	2002 February	23	2	148
Refinishing wheels	1998 April	26	4	20
Tire bead breaker	1999 October	33		62
Tire clearance	2000 February	26	2	70
Tire pressure	2002 June	32		168
Tire purchase	2000 December	23	5	98
Tire sizes	2005 May	32		270
Tire sizes part 2	2004 June	25	1	234
Tire rotation	2000 April	32		80
Tires needed	2000 February	28	4	71
Uneven tire tread wear	2003 August	31		211
Wire wheel conversion	2001 February	23	3	105
Wire wheel conversion part 2	2001 October	27		138
Wire wheel inspection	2000 April	33		81