

- 1. Make top piece first and form into cone
- 2. Stitch cone to base ring
- 3. When placed in the car, seam of cone should run BEHIND the gear lever
- 4. Holes can then be made in the base ring to match screw holes in gear box top cover (threaded plates are located welded to underside of gear box top cover)
- 5. Gaiter is held in place by steel plate ring
- 6. Screw heads and ring should be painted gloss black

NB. This is NOT a template, but a measured drawing. Do not use this to draw around but rather as an indication for measurements. Picture for illustration purposes only.